

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL PROTECTION  
BUREAU OF MINING AND RECLAMATION

Inspection ID # 1125427

Mine Name Rock Hill Quarry

INSPECTION REPORT  
NONCOAL

Date 5/23/02

Weather Sunny ~ 75°F

On Site Times \_\_\_\_\_

PERMITTEE <u>Hanson Aggregates of Pa Inc.</u>	TOWNSHIP <u>East Rock Hill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745m1</u>
ADDRESS <u>1900 Sullivan Trail Easton Pa 18040</u>	VIOLATION HISTORY NOV'S _____ CO'S _____		VIOLATIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
<u>610-253-4271</u>			LICENSE NO. & EXP. DATE <u>1848</u> OPERATIONAL STATUS

GENERAL MINING INFORMATION: Large Noncoal  Small Noncoal \_\_\_\_\_ Complete  Partial or Followup \_\_\_\_\_

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: Dabase OPEN Pit ~1500' x 900' x 250'

b. Acreage (total): Bonded 103.2 Affected ~103 Regraded  Reclaimed

c. Equipment-Use & Conditions: Excavator

d. Contract Miner  yes  no e. Blasting at Site  yes  no (Explain yes answers)

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
NA	700 Unauthorized Mining				NA	730 Concurrent Reclamation			
✓	701 Signs and Markers					731 Backfilling and Grading			
✓	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat.			
✓	703 Topsoil-Rem/Sto/Hndlng					735 Revegetation			
✓	704 Effluent Standard					742 Permanent Mining Cessation			
✓	706 Diversions and Conveyance					743 Haul Roads/Restoration			
✓	707 Sediment Control Measures				✓	745 Support Facilities			
NA	708 Treatment Facilities				✓	749 General Safety			
✓	709 Sedimentation Ponds				✓	753 Permit Conditions			
✓	710 Discharge Structures				NA	754 Temporary Mining Cessation			
NA	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
✓	712 Impoundments				✓	756 Distance Limitations-Barriers			
✓	713 Dams, Ponds-Design/Const./Maint.				✓	757 Bench Development			
✓	715 Water Monitoring-Ground/Surface				✓	758 Permit Line Setback			
NA	717 Water Rights and Replacement				NA	759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
✓	727 Disposal of Solid Wastes					762 Cleanup			
✓	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS:

Person Contacted	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected <u>0</u> to <u>0</u>
Signature <u>Mailed</u>	Investigator Signature & I.D. No. <u>Ewy # 411545</u>	<u>4</u> <u>5</u> <u>1</u> <u>2</u>

### COMMENTS AND RECOMMENDATIONS

Mine Name \_\_\_\_\_

Date 5/23/02


PERMITTEE	TOWNSHIP	COUNTY	PERMIT NO.
Hanson Aggregates of Pa, Inc.	East Rock Hill	Bucks.	79745m1

Mining operations at this permit remain idle. The operator is advised that a minimum of 500 tons of material must be mined this year or a request for a temporary cessation must be submitted to the Pottsville District Office.

The operator is advised that the T.D sign has been removed from the wooden frame and will need to be replaced. The sign should be visible from the public roadway.

No EAS control problems noted and there was no discharge from monitoring point 001. (MPDES# PA0594121 expires 7/19/03)

Violation History: None

Person Contacted	Title	Investigator Signature & I.D. No.
Signature	 <input type="checkbox"/> <input checked="" type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.