

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

Non Coal
INSPECTION REPORT

Date 11-2-84

7-8

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diabase
- b. Highwall/s height/s: actual 250 ft. = 5 lifts
bonded _____
- c. Length & Width of cut/s 1500 X 775 ft.
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: none

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition SAME

4. Contract Miner Name: _____
 yes no Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>GARRY TAYLOR</u> Signature	Title <u>COAL MGR</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Investigator <u>James Carpenter</u> Signature		<u>46106</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

NONE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 11-2-84

Permit Number <u>7976SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
Name of Permittee <u>The General Crushed Stone Co.</u>		
C. Comments & Recommendations		

WATER IN PIT app 85' ± This means that
2 levels will be under water soon.

There is still quite a bit of stock on
Surge pile.

Operator Larry V. Taylor 11/2/84 Inspector James Carpenter
Signature Date Signature