PERMIT NO.

7974SM1

PERMITTEE

COMMONWEALTH OF PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry Weather Clear 50 F

Hanson Aggregates of Pa., Inc.

INSPECTION REPORT NONCOAL

TOWNSHIP

East Rockhill

COUNTY

Bucks

Page 1 of 1 Date 11/2/2009 On Site Times AM

ADDRESS	VIOLATION		VIOLATIONS NOTED ☐ FOLLOW-UP INSP. REQUIRED ☐ PREVIOUS VIOLATIONS: COMPLIANCE ORDER ☐			LICENSE NO. & EXP. DATE 1848 12/31/2009		
2900 Terminal Ave.						OPERATIONAL STATUS		
Richmond VA 23234 804-221-3781	0CO,8					Active		
OCALEDAL MINING INCODMATION.	_	- 1					OWIL	n 🗆
GENERAL MINING INFORMATION: Large Noncoal ☑ Small Noncoal ☑ Complete ☑ Partial or Followup ☑ a. Areas-Minerals-Pit Dimensions (L/W/H) – Method: Diabase Open Pit ~ 1500' (457m) x 900' (274m) x 250' (76m)								
b. Acreage (total): 103.3 (41.77ha) Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0								
c. Equipment-Use & Conditions: No equipment on site								
d. Contract Miner ☐ yes ⊠ no	e. I	3lasti	ng at Site [X∣ ye	s no (Explain yes answer) No rece	<u>ent blastinç</u>	İ	
PERFORMANCE STANDARDS NONCOAL								
Obs. STANDARD	PC or Reg.				STANDARD	PC or Reg.	Viol.	Comp. Date
	O Or reg.	VIOI.	Comp. Date		730 Concurrent Reclamation			
X 700 Unauthorized Mining X 701 Signs and Markers						<u> </u>		
NA 702 Casing and Sealing Drilled Holes			.,		733 Covering Coal and Acid/Toxic Mat.			
X 703 Topsoil-Rem/Sto/HnIng					735 Revegetation			
X 704 Effluent Standard	1				742 Permanent Mining Cessation			
NA 706 Diversions and Conveyance				X	743 Haul Roads/Restoration			
X 707 Sediment Control Measures				X	745 Support Facilities			
NA 708 Treatment Facilities				Х	749 General Safety	·		
X 709 Sedimentation Ponds				X	753 Permit Conditions		ļ.,	
X 710 Discharge Structures				NA	754 Temporary Mining Cessation			.,
NA 711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
NA 712 Impoundments				Х	756 Distance Limitations-Barriers	!	<u> </u>	
NA 713 Dams, Ponds-Design/Const./Maint.				X	757 Bench		ļ	-
NA 715 Water Monitoring-Ground/Surface		ļ		X	758 Permit Line Setback			
NA 717 Water Rights and Replacement		ļ			759 Stability Analysis			
NA 718 Water Discharge-Underground Mine		<u> </u>			760 Post Mining Renovation 761 Postmining Land Use		 	
X 723 Blasting Requirement X 727 Disposal of Solid Wastes				NA NA				
X 727 Disposal of Solid Wastes X 728 Air Resources Protection				19/5	702 Oscariup			
A 1/26 Air Resources Florection		1					L	
COMMENTS AND RECOMMENDATI	ONS: Thi	s con	nplete inspe	ction	was conducted solo. The gate wa	s locked.	No a	ctivity
was observed.	-							•
A CONTRACTOR OF THE PROPERTY O								
			•					
						-		
Violation History: None								
VIOIGION CHISTORY. NONE					•			
						-		
D-ver Contested	Title			Die	charge/Seeps 🔲 yes 🔀 no			
Person Contacted	ritie				· · · — <u>·</u> —			
					mples Collected yes no			
None					nge of Samples Collected			
Signature				Inv	estigator Signature	Sampler I	.D. N	lo. 4519
_					AVI			
Mailed				Am	niee Bollinger (1 A	Employee #608058		
5								•
The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the								

investigator. The signature does not necessarily mean he agrees with the report.