

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry
Weather Sunny 45°

INSPECTION REPORT
NONCOAL

Date 11/22/00
On Site Times AM

PERMITTEE <u>HANSON AGGREGATES OF PA, INC.</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>1900 SULLIVAN TRAIL EASON, PA. 18040</u> <u>610-253-4271</u>	VIOLETION HISTORY <u>0</u> NOV'S <u>0</u> CO'S	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>3-00679 9/30/01</u> OPERATIONAL STATUS <u>Idle</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: DIMENSION - OPEN PIT
N 1500' (457m) x 900' (274m) x 250' (76m) 5 levels
1033 (41.7ha)

b. Acreage (total): 1 Bonded 103.2 Affected ~103 Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: PROCESSING PLANT

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NO RECENT BLASTING

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining				<u>NA</u>	730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers				<input checked="" type="checkbox"/>	731 Backfilling and Grading			
<u>NA</u>	702 Casing and Sealing Drilled Holes				<input checked="" type="checkbox"/>	733 Covering Coal and Acid/Toxic Mat.			
<u>NA</u>	703 Topsoil-Rem/Sto/Hnding				<input checked="" type="checkbox"/>	735 Revegetation			
<input checked="" type="checkbox"/>	704 Effluent Standard				<input checked="" type="checkbox"/>	742 Permanent Mining Cessation			
<u>NA</u>	706 Diversions and Conveyance				<input checked="" type="checkbox"/>	743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
<u>NA</u>	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
<u>NA</u>	710 Discharge Structures				<u>NA</u>	754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil				<u>NA</u>	755 Closing Underground Mine Openings			
	712 Impoundments				<input checked="" type="checkbox"/>	756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const./Maint.				<input checked="" type="checkbox"/>	757 Bench Development			
	715 Water Monitoring-Ground/Surface				<input checked="" type="checkbox"/>	758 Permit Line Setback			
	717 Water Rights and Replacement				<u>NA</u>	759 Stability Analysis			
<input checked="" type="checkbox"/>	718 Water Discharge-Underground Mine				<input checked="" type="checkbox"/>	760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: THIS INSPECTION CONDUCTED "SOLO". (1) ID SIGN HAS FALLEN DOWN AND SHOULD BE REPAIRED ASAP. (2) NO ACTIVITY ON SITE - OPERATOR CALLED EARLY SEPT, STARTING 500 TONS OF MATERIAL WOULD BE REMOVED - EVIDENCE OF THIS OBSERVED. (3) RECEIVED MESSAGE OF PLAN TO APPLY FOR TEMPORARY MINING CESSATION. (4) E+S CONTROLS ADEQUATE - NO DISCHARGE OBSERVED - ALL SED PONDS SHOULD SOON BE CLEANED. (5) NO BLASTING SINCE LAST INSPECTION (6) NO VIOLATIONS

Person Contacted <u>None.</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
Signature <u>MAILRO 11/22/00</u>	Investigator Signature & I.D. No. <u>D. Walter 149238</u>	<u>4 5 3 2</u>