ER-MR-5
REV. 2/74

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mining Permit No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 6-82

Company	Mine Location: County	Township
General Crushed Stone Co	Bucks	E. Rockhill

Mining Permit Acres Affected	Drainage Permit Acres Affected
95	

Status of Operation: Active	Inactive	Not Started
X		

1. Is this operation in compliance with the Safety Rules and Regulations? YES ✓ NO ____ NOTED ____
2. Is this mine operating in compliance with the conditions of the mining permit YES ✓ NO ____ NOTED ____
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES ✓ NO ____ NOTED ____

REMARKS AND RECOMMENDATIONS:

There was no one on site at time of inspection - 8:30-11:30 AM

Not pumping - water rising?

I found no S+E problems

Company Official Contacted: Copy mailed
Title:
Mine Inspector: James Carpenter
Inspection Date: 11-26-82

INSPECTORS' RECOMMENDATIONS TO BUREAU:

CENTRAL OFFICE-MINE DRAINAGE