

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

5

INSPECTION REPORT

Date 10-4-83

PERMITTEE The General Crushed Stone Company	TOWNSHIP East Rockhill	COUNTY Sucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pennsylvania 18042	TYPE OF INSPECTION Partial <input checked="" type="checkbox"/> Followup <input type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. 300733 Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date 1-1-84 Operational Status ACTIVE

A1. GENERAL MINING INFORMATION

- a. Seams BASTARD TRAP ROCK (DIA BASE)
- b. Highwall/s height/s: actual 5 BENCHES 250'  
bonded N/A
- c. Length & Width of cut/s 1500' X 975'
- d. Total Acres: Permitted N/A Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining \_\_\_\_\_ Acres  Unauthorized Mining Activities \_\_\_\_\_ Acres

2. Method of Mining: TRUCK TO CRUSHER WHEN CRUSHING  
NEW SELLING STOCK

3. Equipment: Use & Condition 2 FRONT END LOADERS - GOOD CONDITION  
1 TRUCK SHOVEL

4. Contract Miner Name: \_\_\_\_\_  
 yes  no Address: \_\_\_\_\_

5. Blasting at Site:  yes  no Blaster's Name \_\_\_\_\_ License No. \_\_\_\_\_  
Contract Blaster  yes  no Contractors name \_\_\_\_\_

6. Auger Permit Safety Permit No. \_\_\_\_\_  
 yes  no  Active  Inactive  not started  completed

7. Refuse Disposal Approved  
 yes  no  Active (describe)  Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding  yes  no Type \_\_\_\_\_
- b. Adjudications Outstanding  yes  no Type \_\_\_\_\_
- c. Violations on Last Inspection  yes  no (If yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u>	Title <u>O.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Signature <u>Joseph Bronico</u>	Investigator <u>James Carpenter</u>	Signature <u>James Carpenter</u> I.D. No. <u>7451016</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA  
DEPARTMENT OF ENVIRONMENTAL RESOURCES  
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-4-83

Permit Number  
797ASM1

Township  
East Rockhill

County  
Bucks

Name of Permittee  
The General Crushed Stone Company

C. Comments & Recommendations

*NOT OPERATING QUARRY - loading from STOCK*

*HAVE BILL CHECK MDP Acreage*

Operator *James Brown*  
Signature

10/4/83  
Date

Inspector *Jonas Carpenter*  
Signature