

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 9-23-87

| | | | |
|--|---|---|--|
| PERMITTEE <u>The General Crushed Stone Co.</u> | TOWNSHIP <u>EAST ROCKHILL</u> | COUNTY <u>BLUES</u> | PERMIT NO. <u>7974 SM1</u> |
| ADDRESS <u>P.O. BOX 231 EASTON, PA 18042 215-253-4271</u> | TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/> | STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/> | LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-87</u> Operational Status <u>ACTIVE</u> |

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 200' - 5 LEVELS
bonded 101,700
- c. Length & Width of cut/s 1580' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded Reclaimed
- e. Phase/s being mined: 733-5

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition FEL.

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

| | | |
|--|------------------------|---|
| Person contacted <u>GARY V. TAYLOR</u> Signature | Title <u>F.C.M.</u> | Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached. |
| Investigator <u>Janos Carpenter</u> Signature | | I.D. No. <u>415016</u> |

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the Investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 9-23-87

Permit Number 7974SM1 Township EAST ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone, Co

C. Comments & Recommendations

This mine has not operated in years
& there has been no blasting -
WATER LEVEL IN PIT HAS NOT CHANGED
IN MY OPINION:
There is no problems with S + E
CONTROLS AT PRESENT:
I D SIGN PASTED

Operator Larry Taylor Signature Date 9/23/87 Inspector James Carpenter Signature