

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini permit No. 733-5
Drainage Permit No. 7974 SMI
Mine Inspection No. 54
Reinspection No. 3-78

Company <u>General Crushed Stone Co</u>		Mine Location: County <u>Bucks</u>	Township <u>E. Rockhill</u>
Mining Permit Acres Affected <u>15</u>		Drainage Permit Acres Affected <u>30</u>	
Status of Operation: Active <u>X</u>	Inactive	Not Started	

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO _____ NOTED _____
2. Is this mine operating in compliance with the conditions of the mining permit? YES _____ NO _____ NOTED _____
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES _____ NO _____ NOTED X

REMARKS AND RECOMMENDATIONS: Discharge clear.
Basin has been dug near the spur line switch for the storage yard area. Drainage is to be directed to this basin. Use of waste dump has been discontinued and reclamation of site is in order. Broken windshield on Cat 988 and on Mack trucks have been replaced. Test hole drilled on "woods road" is to be plugged immediately - used by riders (hoof prints show near hole) Drainage from SE area (storage etc) to be controlled. A 25' safety bench must be maintained between successive faces where multiple benchings.

Foreman/Official/Consultant: James Fryer
 Mine Inspector: Paul T. Seifert
 Title: Supt.
 Inspection Date: Sept. 25, 1978

INSPECTORS' RECOMMENDATIONS TO BUREAU:
Conditions noted on Reinspection Report # 2-78 have been corrected.
What is the criteria for the discharge under Industrial Waste Permit # 0971205? Please give an answer to the Dist. #54 Inspector