

STATE SENATOR
STEVE SANTARSIERO
10TH SENATORIAL DISTRICT

- SENATE BOX 203010
THE STATE CAPITOL
HARRISBURG, PA 17120-3010
717-787-7305
FAX: 717-783-5962
- 3 TERRY DRIVE, SUITE 201
NEWTOWN, PA 18940
215-497-9490
- 2003 LOWER STATE ROAD
BUILDING 100, SUITE 121
DOYLESTOWN, PA 18901
215-489-5000



Senate of Pennsylvania

COMMITTEES

**COMMUNICATIONS & TECHNOLOGY,
DEMOCRATIC CHAIR
APPROPRIATIONS
CONSUMER PROTECTION
& PROFESSIONAL LICENSURE
JUDICIARY
LOCAL GOVERNMENT**

E-MAIL: SenatorSantarsiero@pasenate.com
FACEBOOK: www.facebook.com/SenSantarsiero
TWITTER: @SenSantarsiero
INSTAGRAM: @Senator_SteveSantarsiero
WEB: www.senatorstevesantarsiero.com

June 21, 2019

Via Email and Regular Mail

Gary Latsha
Acting Mining Manager
PENNSYLVANIA DEPARTMENT OF ENVIRONMENTAL PROTECTION
Pottsville District Mining Operations
5 West Laurel Boulevard
Pottsville, PA 17901

Re: Rockhill Quarry

Dear Mr. Latsha,

I am writing to follow up on our discussion at the June 14 meeting at the DEP's Southeast Regional Office in Norristown regarding the historical operation of the Rockhill Quarry (the "Quarry"). At that meeting, Mr. Stefanko stated that it was the Department's position that the Quarry has been in continuous operation since the early 1980s. Based on the information that my office and others have obtained to date, I believe that the Department is incorrect on that point.

The Department's annual state-wide quarry reports show that in two years, 1983 and 1986, fewer than 500 tons of material were removed from the Quarry (i.e., zero tons in 1983 and 180 tons in 1986). Copies of the relevant pages of those reports are enclosed for your convenience.

To date we have not received any underlying documentation pertaining to activity at the Quarry for those years save three 1986 inspection reports signed by a Jonas Carpenter, who appears to have been the Department's inspector at the site until at least early 1996. The July 24, 1986 report states in the comments section that "[the operators] have removed over 500 ton [sic] from stock this year to keep permit active." Similarly, according to the October 30, 1986 inspection report "[t]hey state they will keep operation active by removing a minimum of 500 tons of material per year." Copies of both inspection reports are also enclosed.

It would appear that in both instances the inspector was merely repeating what the operators had told him – without offering him any proof – while he was performing his inspection. We are aware of no documents that would support the claim that the Quarry’s operators were in fact removing a minimum of 500 tons of material from the Quarry in either 1983 or 1986. **Indeed, as noted, the Department’s own annual reports contradict that assertion.** Please provide us with all evidence supporting the Department’s conclusion that the site’s operators removed a minimum of 500 tons of material from the Quarry in 1983 and 1986.

For the years 1984, 1987, 1993, 1995 and 1996 there are no annual reports available. There are, however, inspection reports for those years. While the inspection reports list the Quarry as “active” in the operational status box on the forms, they do not mention whether a minimum of 500 tons of material were in fact being removed during those years. On the contrary, the reports have numerous comments which suggest the opposite:

- July 16, 1984 inspection report states “[t]hey have not did [sic] any quarrying in over 2 years – they still have material in stock which they are moving *slowly*.” [Emphasis added.]
- November 2, 1984 inspection report states “[t]here is still quite a bit of stone on storage pile.”
- September 23, 1987 inspection report states that “[t]his mine has not operated in years and there has been no blasting.”
- October 23, 1993 inspection report states “[n]o one on site.”
- Each of the inspection reports from 1995 include the notation “[n]o one on site” and three of them note that the gate was locked.
- February 5, 1996 inspection report (the last one that Mr. Carpenter filled out) states “[n]o one on site.”
- December 11, 1996 inspection report by John Emlick has the inscription “[a]ctive ??” in the operational status block. The notes section of that report reads, in relevant part that “[s]ite entrance has gate locked. No one on site. Garage, scalehouse and other buildings are boarded closed. This site has not been worked since 1991-2 as determined from past inspection reports. Inspector will contact Operator to verify that a minimum of 500 tons of material has been removed from site in order to retain an active status.”

All of these inspection reports are enclosed for your convenience.

Please provide us with all evidence supporting the Department's conclusion that the site's operators removed at least 500 tons of material from the Quarry during these years and, in particular, any information regarding inspector Emlick's attempts to follow up with the Quarry's operator after his December 11, 1996 inspection. *

At the June 14 meeting, in response to Congressman Fitzpatrick's question, the Department acknowledged that the site is one of only two quarries in Pennsylvania in which asbestos has been found and, likely, the only one in a residential area. In light of that fact and the potential risk to residents' health and safety that this Quarry represents, it is particularly important that the issues raised here be addressed as quickly as possible. Toward that end, I would ask that the Department provide us with the information we have requested in this letter by July 15, at the latest.

Thank you.

Very truly yours,



Steven J. Santarsiero
State Senator, 10th District

Enclosures

CC (via email w/encls):

Michael Brunelle, Office of the Governor, Chief of Staff
Will Danowski, Office of the Governor, Secretary of Legislative Affairs
Congressman Brian Fitzpatrick
State Senator Bob Mensch
State Representative Craig T. Staats, Pennsylvania Representative
Secretary Patrick McDonnell, PA DEP
Marianne Morano, East Rockhill Township, Manager
Megan Banis-Clemens, Pennridge School Board, President
Patrick Patterson, PA DEP, Southeast Regional Director
Robert Fogel, PA DEP, Southeast Region Local Government Liaison
Katie Zackon, Rockhill Environmental Preservation Alliance

1983

BUCKS COUNTY

Operators and Mines/ or Mine Drainage Permit No.	Production of Minerals -- Net Tons					No. of Em- ployes	Tonnage of Minerals Shipped to			Fatal Acci- dents	Non- Fatal Acci- dents
	Shipped to Market:			Total	Aver-		Foreign	In-State	Out-of		
	By Rail	By Water	By Truck	Production of Minerals Mined for Year	age Days Worked		Markets	Markets	State Markets		
American Olean Tile Co. 7974SM6	-	-	-	37,164	26	6	-	-	-	-	-
Better Materials Corp. 7973SM2	-	-	1,268,489	1,217,489	182	21	-	507,395	761,094	-	1
Edison Quarry 7975SM4	-	-	37,000	35,200	250	5	-	37,000	-	-	-
The General Crushed Stone Co. 7974SM1	-	-	-	-	-	2	-	-	-	-	-
Miller Quarries 7973SM3	-	-	388,978	432,198	210	14	-	388,978	-	-	2
New Hope Crushed Stone Co. 7974SM3	-	-	436,960	462,015	249	13	-	36,960	400,000	-	-
Silvi Concrete Products, Inc. 5476SM5	-	-	92,000	92,000	152	2	-	92,000	-	-	-
Warner Co. 7975SM5	-	-	1,289,400	200	30	-	989,400	300,000	-	-	-
COUNTY TOTAL	-	-	3,512,827	2,276,266	137	73	989,400	1,362,333	1,161,094	-	3

383

1986

BUCKS COUNTY

Operators and Mines/ or Mine Drainage Permit No.	Production of Minerals -- Net Tons					No. of Em- ployes	Tonnage of Minerals Shipped to			Fatal Acci- dents	
	Shipped to Market		Total	Aver-	Foreign		In-State	Out-of-	Fatal		
	By Rail	By Water	Production of Minerals Mined for Year	age Days Worked	Markets		Markets	State Markets	Acci- dents		
American Olean Tile Company 7974SM6	0	0	20,725	20,725	18	6	0	0	0	0	0
Better Materials Corp. 7971SM2	0	0	1,564,349	1,564,349	201	25	0	916,913	0	0	0
Blooming Glen Quarry 7975SM1	0	0	570,700	570,700	244	30	0	570,700	0	0	0
Colony Materials A17975SM2	0	0	79,500	79,500	178	6	0	79,500	0	0	0
Delaware Quarries 09832601	0	0	2,000	2,000	100	2	0	0	0	0	0
Delaware Valley Landscape 09830301	0	0	82,801	82,801	180	10	0	0	0	0	0
G.R.O.W.S., Inc. 09840301	0	0	0	0	270	50	0	0	0	0	0
General Crushed Stone Rk Hil 7974SH1	0	0	180	180	0	10	0	180	0	0	0
H & E Materials 7974SM5	0	0	456,700	456,700	230	10	0	456,700	0	0	0
Langhorne Stone Co. 09832501	0	0	0	0	45	3	0	0	0	0	0
M & H Stone Company 7974SM4	0	0	652,000	652,000	270	28	0	552,000	0	0	0
Miller Quarries 7973SM3	0	0	449,316	449,316	202	14	0	449,316	0	0	0
New Hope Crushed Stone & Lime 7974SM3	0	0	650,000	650,000	250	25	0	75,000	0	0	0
Warner Company 7975SM5	0	0	1,540,000	1,540,000	240	35	0	1,000,000	0	0	0
COUNTY TOTAL	0	0	6,068,271	6,068,271		240	0	4,099,609	0	0	0

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mini mit No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 1-83

Company <u>General Crushed Stone Co</u>	Mine Location: County <u>1 Bucks</u>	Township <u>E Rockhill</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: Active	Inactive <u>X</u>	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO _____ NOTED _____
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO _____ NOTED _____
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO _____ NOTED _____

REMARKS AND RECOMMENDATIONS:

Quarry closed LACK of BUSINESS -

STONE REMAINING IN STOCK NOT BEING SOLD AT PRESENT -

License # supplied from main office

DYNAMITE STORAGE #1617
Cap STORAGE #1616
LICENCES TO PURCHASE #1770

Company Official Contacted <u>Joseph P Bruner Jr</u>	Title <u>Office Manager, Contractor</u>
Mine Inspector <u>James Carpenter</u>	Inspection Date <u>2-16-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

5-5A-5A2 ALL closed

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Mine Permit No. 733-5
Drainage Permit No. 79745M1
Mine Inspection No. 54
Reinspection No. 2-83

Company <u>GENERAL CRUSHED STONE</u>	Mine Location: County <u>BUCKS</u>	Township <u>E ROCKHILL</u>
Mining Permit Acres Affected <u>95</u>	Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO ___ NOTED ___
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO ___ NOTED ___
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO ___ NOTED ___

REMARKS AND RECOMMENDATIONS: FRONT END LOADER LOADING FROM STOCK PILE

WATER IN PIT PUMP CHECK - 45' DEEP -

I FOUND NO S + E PROBLEMS

Company Official Contacted <u>Judy W. Smergart</u>	Title <u>Dispatcher</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>4-28-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

Min. mit No. 733-5
Drainage Permit No. 7974SM1
Mine Inspection No. 54
Reinspection No. 3-83

Company <u>General Crushed Stone</u>	Mine Location: County <u>Bucks</u>	Township <u>E. Rockhill</u>
Mining Permit Acres Affected <u>95-3-5.2</u>	Drainage Permit Acres Affected	
Status of Operation: Active <u>X</u>	Inactive <u>X</u>	Not Started

1. Is this operation in compliance with the Safety Rules and Regulations? YES X NO _____ NOTED _____
2. Is this mine operating in compliance with the conditions of the mining permit? YES X NO _____ NOTED _____
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES X NO _____ NOTED _____

REMARKS AND RECOMMENDATIONS: WATER IN PIT Sump Covers
BOTTOM level-

I FOUND NO S+E Problems
ASPHALT PLANT Removed.
STONE ON STOCKPILES
Office Mgr. Wey 10WE ON SITE

Company Official Contacted <u>Joseph P. Brown</u>	Title <u>Office Manager</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>6-21-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:
none

Commonwealth of Pennsylvania

DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF SURFACE MINE RECLAMATION
INSPECTION
REPORT

C. Ann
field

Mini Permit No. 733-5
Drainage Permit No. 79745M1
Mine Inspection No. 54
Reinspection No. 4-83

Company <u>General Crushed Stone</u>	Mine Location: County <u>Bucks</u>	Township <u>E Rockhill</u>
Mining Permit Acres Affected <u>95-3-5.2</u>	Drainage Permit Acres Affected	
Status of Operation: Active <input checked="" type="checkbox"/>	Inactive <input type="checkbox"/>	Not Started <input type="checkbox"/>

1. Is this operation in compliance with the Safety Rules and Regulations? YES NO NOTED
2. Is this mine operating in compliance with the conditions of the mining permit? YES NO NOTED
3. Is the mine operating in compliance with the conditions of the mine drainage permit? YES NO NOTED

REMARKS AND RECOMMENDATIONS: QUARRY NOT OPERATING
MATERIAL REMOVED FROM STOCK SINCE
LAST INSPECTION
WATER IN PIT CLEAR
I FOUND NO S + E PROBLEMS-

Company Official Contacted <u>Joseph P. Burch</u>	Title <u>Office Manager</u>
Mine Inspector <u>Jonas Carpenter</u>	Inspection Date <u>7-28-83</u>

INSPECTORS' RECOMMENDATIONS TO BUREAU:

NONE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

5

OFFICIAL USE ONLY

HW

INSPECTION REPORT

Date 10-4-83

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>East Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. Box 231 Easton, Pennsylvania 18042</u>	TYPE OF INSPECTION Partial <input checked="" type="checkbox"/> Followup <input type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>1-1-84</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams BASTARD TRAP ROCK (DIA BASE)
- b. Highwall/s height/s: actual 5 benches 250'
bonded N/A
- c. Length & Width of cut/s 1500' x 975'
- d. Total Acres: Permitted N/A Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining _____ Acres Unauthorized Mining Activities _____ Acres

2. Method of Mining: TRUCK TO CRUSHER WHEN CRUSHING
NOW SELLING STOCKS

3. Equipment: Use & Condition 2 FRONT END LOADERS - good COND. TRUCK
1-TRUCK SHOVEL

4. Contract Miner Name: _____
 yes no Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>Joseph Bromico</u>	Title <u>O.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Signature <u>Joseph Bromico</u>	Investigator <u>James Carpenter</u>	Signature <u>James Carpenter</u> I.D. No. <u>4151016</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-4-83

Permit Number <u>7974SM1</u>	Township <u>East Rockhill</u>	County <u>Bucks</u>
---------------------------------	----------------------------------	------------------------

Name of Permittee
The General Crushed Stone Company

C. Comments & Recommendations

NOT OPERATING. QUARRY - heading from STOCK

HAVE BILL CHECK MDP Acreage

Operator

James Brown
Signature

10/4/83
Date

Inspector

James Carpenter
Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 12-2-83

Permit Number <u>79745M1</u>	Township <u>East Rockhill</u>	County <u>Bucks</u>
---------------------------------	----------------------------------	------------------------

Name of Permittee
The General Crushed Stone Company

C. Comments & Recommendations

There is no crushing at this quarry -
There has been none for quite some time.
The only activity at present is loading
stone from stock.

The bottom left of the quarry is now
covered with water over 50'

I found no S + E problems

Operator Joseph P. Brown Signature 12/2/83 Date Inspector Jonas Carpenter Signature

COMMONWEALTH OF PENNSYLVANIA
 DEPARTMENT OF ENVIRONMENTAL RESOURCES
 BUREAU OF MINING AND RECLAMATION
 Non Coal

A

OFFICIAL USE ONLY

INSPECTION REPORT

Date 2-2-84

PERMITTEE The General Crushed Stone Co. ADDRESS P.O. Box 231 Easton, Pa. 18042	TOWNSHIP East Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. 300735 Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u>	Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Dabase
 - b. Highwall/s height/s: actual 5 lifts to 259 ft
bonded _____
 - c. Length & Width of cut/s 1500 X 775 ft.
 - d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
 - e. Phase/s being mined: 733
- Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition SAME

4. Contract Miner Name: _____
 yes no Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
 Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>RICK FRANK</u>	Title <u>GEN SUPT</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Signature <u>Rick Frank</u>		Investigator <u>James Carpenter</u> Signature <u>[Signature]</u> <u>715726</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

NONE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 2-2-84

Permit Number <u>7974SM1</u>	Township <u>East Rockhill</u>	County <u>Bucks</u>
---------------------------------	----------------------------------	------------------------

Name of Permittee
The General Crushed Stone Company

C. Comments & Recommendations

ID Sign Posted.

There has been no BLASTING AT THIS SITE for quite some time - There is no explosives kept on site at present

No water is being pumped -

Stack piles are dwindling -

Operator

[Signature] 2/2/84
Signature Date

Inspector

[Signature]
Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

Non Coal

INSPECTION REPORT

Date 4-4-84
goc

PERMITTEE The General Crushes Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 797LSM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-84</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Diabase
- b. Highwall/s height/s: actual 250 ft = 5 lifts.
bonded _____
- c. Length & Width of cut/s 1500 X 775 ft.
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: 733-1

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarrying

3. Equipment: Use & Condition Same

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted	Title	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
Signature <u>Jack Frank</u>		Investigator <u>James Carpenter</u> Signature <u>45107</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

None

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 4-4-84

Permit Number <u>7974SME</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
---------------------------------	--------------------------------	------------------------

Name of Permittee
The General Crushed Stone Company

C. Comments & Recommendations

ID Sign Posted

There are no explosive stored at this mine - no blasting since last insp -

The water in the quarry is now app. 65' deep. RISING ON 2nd lift -

Stock piles nearing depletion

Operator Pick Frank 4/4/84 Inspector James Carpenter

Signature Date Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION
Non Coal

OFFICIAL USE ONLY

INSPECTION REPORT

Date 7-16-84
8-9

PERMITTEE The General Crushed Stone Co.	TOWNSHIP E. Rockhill	COUNTY Bucks	PERMIT NO. 7974SM1
ADDRESS P.O. Box 231 Easton, Pa. 18042	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. 300733 Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date 12-31-84 Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams Dabase
 - b. Highwall/s height/s: actual 250 ft. = 5 lifts
bonded _____
 - c. Length & Width of cut/s 1500 X 775 ft.
 - d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
 - e. Phase/s being mined: 733-1
- Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: Quarring

3. Equipment: Use & Condition SAM

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved yes no Active (describe) Inactive

- 8. Previous Enforcement:
 - a. Orders & Agreements outstanding yes no Type _____
 - b. Adjudications Outstanding yes no Type _____
 - c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>Joseph Bronico</u> Signature	Title <u>of mgr</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.1 attached.
<u>Joseph Bronico</u> Signature	Investigator <u>James Carpenter</u> Signature	<u>4026</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 7-16-84

Permit Number
7974SM1

Township
E. Rockhill

County
Bucks

Name of Permittee

The General Crushed Stone Co.

C. Comments & Recommendations

Sign posted

There has been no blasting -

Water in pit now off 75'

They have not did any quarrying in over 2 yrs -
They still have material in stock which they
are moving slowly -

I found no STE problems

Operator

Paul Bremer
Signature

7/16/84
Date

Inspector

James Carpenter
Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 11-2-84

Permit Number <u>7974SM1</u>	Township <u>E. Rockhill</u>	County <u>Bucks</u>
Name of Permittee <u>The General Crushed Stone Co.</u>		

C. Comments & Recommendations

WATER IN PIT app 85' ± This means that
2 levels will be under water soon ±

There is still quite a bit of stone on
Storage pile ±

Operator Gary Taylor Signature 11/2/84 Date Inspector Jonas Carpenter Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 7-24-86

PERMITTEE <u>The General Crusted</u> ADDRESS <u>STONE CO.</u> <u>P.O. Box 231</u> <u>EASTON, PA. 18042</u> <u>215-253-4271</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974SM1</u>
TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>		STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-76</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 250' - 5 levels -
bonded 101,700
- c. Length & Width of cut/s 1500' x 775'
- d. Total Acres: Permitted 103.2(103.2) Affected ALL Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition F.E.L.

Good

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>JOSEPH BRONICO -</u> Signature <u>Joseph Bronico</u>	Title <u>D.F. Mgr.</u> - of _____	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
		Investigator <u>Jonas Carpenter</u> Signature <u>[Signature]</u> I.D. No. <u>418206</u>

The operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 7-24-86

Permit Number 7974 SM1 | Township E. ROCKHILL | County BAKES

Name of Permittee The General Crushed Stone Co.

C. Comments & Recommendations

The Crusher or Quarry operation AT
This SITE HAS NOT OPERATED SINCE 1980.
WATER CONTINUES TO ACCUMULATE IN PIT-
3rd level OVER HALF FILLED-

They have Removed over 500 TON
FROM STOCK THIS YEAR TO KEEP PERMIT
ACTIVE-

There was A fault in Berm in back
of crushing plant which was repaired
while inspection was conducted-

I.D. SIGN PASTED-

I Found no problems when inspection
was completed

Operator Joel Bunn | 7/24/86 | Inspector James Carpenter
Signature Date Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date: 10-9-86

PERMITTEE <i>The General Crushed</i>	TOWNSHIP <i>E. ROCKHILL</i>	COUNTY <i>BUCKS</i>	PERMIT NO. <i>79745M1</i>
ADDRESS <i>STONE CO. P.O. Box 231 EASTON, PA 18042 215-253-4271</i>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <i>300733</i> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <i>12-31-86</i> Operational Status

A1. GENERAL MINING INFORMATION

- a. Seams *DIABASE*
- b. Highwall/s height/s: actual *250' - 5 levels*
bonded *101,700*
- c. Length & Width of cut/s *1500' x 775'*
- d. Total Acres: Permitted *103.2 (103.2)* Affected *103.2* Regraded *0* Reclaimed *0*
- e. Phase/s being mined: *NONE*

Unauthorized Mining *0* Acres Unauthorized Mining Activities *0* Acres

2. Method of Mining:

QUARRING

3. Equipment: Use & Condition

FEL.

GOOD

4. Contract Miner

yes no

Name: _____
Address: _____

5. Blasting at Site:

yes no
Contract Blaster yes no

Blaster's Name _____ License No. _____
Contractors name _____

6. Auger Permit

yes no Active Inactive not started completed

7. Refuse Disposal Approved

yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <i>Joseph Bronico</i>	Title <i>Off. mgr</i>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Signature <i>Joseph Bronico</i>	Investigator <i>James Carpenter</i>	<input checked="" type="checkbox"/> I.D. No. <i>41506</i>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-9-86

Permit Number <u>7974 SMI</u>	Township <u>E. ROCKHILL</u>	County <u>BUCKS</u>
Name of Permittee <u>The General Crushed Stone Co</u>		

C. Comments & Recommendations

There has been NO MINING AT THIS SITE
 SINCE LAST INSPECTION
 WATER IN PIT RISING SHOWING, APP 130' OF WATER
 IN PIT -
 I FOUND NO S+E PROBLEMS -
 1 D SIGN POSTED.

Operator Joseph P. Brown Signature Date 10/9/86 Inspector Joyces Carpenter Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 10-30-86

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input checked="" type="checkbox"/> Complete <input type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-86</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 250' - 5 levels
bonded 101,700
- c. Length & Width of cut/s 1500' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: NONE

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: DRILL AND BLEN

3. Equipment: Use & Condition FEL

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permt Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>VERNON R. SNYDER</u>	Title <u>SAFETY DIRECTOR & ENVIRONMENTAL ENG.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected <u>0</u>	ER-MR-5.2 attached.
Signature <u>Vernon R. Snyder</u>		Investigator <u>James Carpenter</u> Signature	<u>46704</u> I.D. No.

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 10-30-86

Permit Number 7974SM1 Township E. ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone Co.

C. Comments & Recommendations

MEETING WITH K. SNYDER, V. SNYDER, T. DEMASI ALLY OF
GENERAL CRUSHED STONE TO DISCUSS OPERATION OF
THIS MINE:

They STATE they will keep OPERATION ACTIVE
by removing a minimum of 500 TONS of MATERIAL
per year! sec. # 2 of ACT 219 - (ACTIVE OPERATION)
& (MINERALS)

Operator Kenn R. Snyder 10/30/86 Inspector Jonas Carpenter
Signature Date Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 2-25-87

PERMITTEE <u>The General Crushed Stone</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>COMPANY</u> <u>P.O. BOX 231</u> <u>EASTON, PA 18042</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>700-783</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-87</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIMBASE
- b. Highwall/s height/s: actual 250' - 5 LEVELS
bonded 101,700
- c. Length & Width of cut/s 1500' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: ADDER 733-5

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition FEL

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>GARY V TAYLOR</u>	Title <u>Field Const. Manager</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
Signature <u>Gary V Taylor</u>	Investigator <u>Jonas Compton</u>	Signature <u>Jonas Compton</u> I.D. No. <u>451016</u>

Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 2-25-87

Permit Number 7974SM1 Township EAST ROCKHILL County BUCKS

Name of Permittee The General Crushed Stone Company

C. Comments & Recommendations

This plant has not operated for years-

Water level in pit app 130' -

I found no S + E problems -

The total area covered by snow.

ID sign posted.

Operator [Signature]
Signature

2/25/87
Date

Inspector [Signature]
Signature

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

OFFICIAL USE ONLY

INSPECTION REPORT

Date 9-23-87

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974 SW1</u>
ADDRESS <u>P.O. BOX 231 EASTON, PA 18042 215-253-4271</u>	TYPE OF INSPECTION Partial <input type="checkbox"/> Followup <input type="checkbox"/> Complete <input checked="" type="checkbox"/>	STATUS Violation/s Noted <input type="checkbox"/> Issue Order <input type="checkbox"/> Cease Order Issued <input type="checkbox"/> Previous Violations not corrected <input type="checkbox"/>	LICENSE NO. <u>300733</u> Valid Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Expiration Date <u>12-31-87</u> Operational Status <u>ACTIVE</u>

A1. GENERAL MINING INFORMATION

- a. Seams DIABASE
- b. Highwall/s height/s: actual 250' 5 LEVELS
bonded 101,700
- c. Length & Width of cut/s 1580' x 775'
- d. Total Acres: Permitted 103.2 (103.2) Affected 103.2 Regraded 0 Reclaimed 0
- e. Phase/s being mined: 733-5

Unauthorized Mining 0 Acres Unauthorized Mining Activities 0 Acres

2. Method of Mining: QUARRING

3. Equipment: Use & Condition FEL.

4. Contract Miner yes no Name: _____ Address: _____

5. Blasting at Site: yes no Blaster's Name _____ License No. _____
Contract Blaster yes no Contractors name _____

6. Auger Permit Safety Permit No. _____
 yes no Active Inactive not started completed

7. Refuse Disposal Approved
 yes no Active (describe) Inactive

8. Previous Enforcement:

- a. Orders & Agreements outstanding yes no Type _____
- b. Adjudications Outstanding yes no Type _____
- c. Violations on Last Inspection yes no (If yes, explain status in remarks)

Person contacted <u>GARY V. TAYLOR</u> Signature	Title <u>F.C.M.</u>	Discharges/Seeps: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no Samples collected: <input type="checkbox"/> yes <input checked="" type="checkbox"/> no No. of samples collected _____ ER-MR-5.2 attached.
<u>Gary V. Taylor</u>		Investigator <u>Janos Carpenter</u> Signature I.D. No. <u>415016</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

INSPECTION REPORT

Date 9-23-87

Permit Number <u>7974SM1</u>	Township <u>EAST ROCKHILL</u>	County <u>TRUCKS</u>
---------------------------------	----------------------------------	-------------------------

Name of Permittee
The General Crushed Stone, Co

C. Comments & Recommendations

This mine has not operated in years
& there has been no blasting -
WATER LEVEL IN PIT HAS NOT CHANGED
IN MY OPINION:

There is no problems with S + E
CONTROLS AT PRESENT:

1 D SIGN PASTED

Operator <u>Larry Taylor</u> Signature	<u>9/23/87</u> Date	Inspector <u>James Carpenter</u> Signature
--	------------------------	--

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 4-1-93

Mine Name ROCK HILL
Weather RAIN

INSPECTION REPORT
NONCOAL

On Site Times AM -

PERMITTEE <u>GENERAL CRUSHED STONE Comp.</u>	TOWNSHIP <u>E. ROCKWILL</u>	COUNTY <u>BULLOCKS</u>	PERMIT NO. <u>79945M1</u>
ADDRESS <u>P.O. BOX 231 1609 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY <u>0 NOV'S 0 CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>300</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <u>733-12-31-93</u>
			OPERATIONAL STATUS <u>ACTIVE</u>

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500' x 900' x 250'-5 TUNNELS OPEN PIT QUARRY TOP 850
W.T. 510
BOT 464

b. Acreage (total): Bonded 103.2 Affected ALL Regraded Reclaimed

c. Equipment-Use & Conditions: FEL

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Store/Handling					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
<input checked="" type="checkbox"/>	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection					<u>0 VIOLATION HISTORY</u>			

COMMENTS AND RECOMMENDATIONS: WATER NOW COVERS ALL BENCHES - DEPT ?
NOTHING AFFECTED
NO PROBLEMS FOUND

Person Contacted <u>MIRIAM ELGINAY</u>	Title <u>OFFICE</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Melgindy</u>	Investigator Signature & I.D. No. <u>Jonas Campaner</u> <u>4506</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
	Range of Samples Collected _____ to _____	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 6-15-93

Mine Name Rock Hill
Weather Clear

INSPECTION REPORT
NONCOAL

On Site Times AM

PERMITTEE <u>The General Crushed Stone</u>	TOWNSHIP <u>E. Rock Hill</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745m1</u>
ADDRESS <u>P.O. Box 231</u> <u>EASTON, PA 18042</u>	VIOLATION HISTORY NOV'S CO'S	VIOLATIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>300</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
LICENSE NO. & EXP. DATE <u>33-12-31-93</u>			OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500'x900'x250' - 5 LIFTS
Open Pit Quarry

b. Acreage (total): Bonded 103.2 Affected: ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: FEL

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) None

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Store/Handling					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO DNR ON SITE

Nothing Affected

Person Contacted <u>Copy office</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy office</u>	Investigator Signature & I.D. No. <u>Jonas Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<input type="checkbox"/> 4 <input type="checkbox"/> 5 <input type="checkbox"/> 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 8-20-93

Mine Name ROCK HILL
Weather 50994

INSPECTION REPORT
NONCOAL

On Site Times Am-

PERMITTEE <u>The GENERAL CRUSHED STONE CO</u>	TOWNSHIP <u>E ROCK HILL</u>	COUNTY <u>-BUCKS</u>	PERMIT NO. <u>79749M1</u>
ADDRESS <u>P.O. BOX 231 160 S. WILKINSON TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>300733-12-31-93</u> OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500' X 900' X 250' 5 LIFTS
OPEN PIT QUARRY

b. Acreage (total): Bonded 103.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: FBI

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: WATER IN DRAINAGE HAS RASED another 5' or more -

NO PERMIT problem observed

Person Contacted <u>MIRIAM ELGINOY OFFICE</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>M Elginoy</u>	Investigator Signature & I.D. No. <u>Jonas Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<u>4 5 0 6</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL
Weather CLEAR

Date 10/25/93

INSPECTION REPORT
NONCOAL

On Site Times Am

PERMITTEE <u>THE GENERAL CRUSHED STEEL COMPANY</u>	TOWNSHIP <u>E. ROCK HILL</u>	COUNTY <u>BERKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231 1609 SULLIVAN TRAIL EASTON, PA - 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
LICENSE NO. & EXP. DATE <u>30733-12-31-93</u>			OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method:
1500 X 900 X 250 - 5' LIFTS
OPEN PIT CRATERY

b. Acreage (total): Bonded 103.2 Affected ALL Regraded Reclaimed

c. Equipment-Use & Conditions:
FEU

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handing					736 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures					<input checked="" type="checkbox"/> 745 Support Facilities			
	708 Treatment Facilities					<input checked="" type="checkbox"/> 749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds					<input checked="" type="checkbox"/> 753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					<input checked="" type="checkbox"/> 762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO DMS ON SITE

WATER up 10.2'
NO PROBLEM OBSERVED

Person Contacted <u>Copy DATED OFFICE</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature	Investigator Signature & I.D. No. <u>James Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 12-28-93

Mine Name ROCK HILL
Weather Cloudy

INSPECTION REPORT
NONCOAL

On Site Times AMS-

PERMITTEE <u>The General Cracked Stone Co.</u>	TOWNSHIP <u>E. Rock Hill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. BOX 231 1609 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLATION HISTORY NOV'S CO'S	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> <u>PO</u> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>733-12-31-93</u>	
		OPERATIONAL STATUS <u>ACTIVE</u>	

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500' x 900' x 5 LIFTS
OPEN PIT DR-

b. Acreage (total): Bonded 103.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: FEL

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NOTHING AFFECTED

WATER RISING

NRPS PERMIT Renew 1992 DATED 30 11:10:25

Person Contacted <u>Miriam Eljandy</u>	Title <u>OFFICE</u>	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Melging</u>	Investigator Signature & I.D. No. <u>James Carpenter</u> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	Range of Samples Collected <u>to</u>	

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 2-3-95

Mine Name ROCK HILL
Weather SUNNY

INSPECTION REPORT
NONCOAL

On Site Times: AMT

PERMITTEE <u>The General Crushed Stone Co.</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>ROUTE 231 1609 SULLIVAN TRAIL EASTON, PA 18042</u>	VIOLETION HISTORY ____NOV'S ____CO'S	VIOLETIONS NOTED <input type="checkbox"/> FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> PREVIOUS VIOLATIONS: COMPLIANCE ORDER <input type="checkbox"/> <u>306</u> CORRECTED <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> UNCORRECTED <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>	LICENSE NO. & EXP. DATE <u>33-12-31-95</u> OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal _____ Complete Partial or Followup _____

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500X900X250-5 LISTS
OPEN PIT QUARRY

b. Acreage (total): Bonded 10412 Affected ALL Regraded 0 Reclaimed

c. Equipment-Use & Conditions: SAME

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hnding					735 Vegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED AT R.R.
NO ONE ON SITE
TRUCKS & CONS. EQUIPMENT PARKED OFF (20)

Person Contacted <u>Copy FILE</u>	Title	Discharge/Sneps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>Copy</u>	Investigator Signature & I.D. No. <u>Lanas Carpenter</u>	Range of Samples Collected: _____ to _____

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name ROSE HILL
Weather Cloudy

INSPECTION REPORT
NONCOAL

Date 4-27-95

On Site Times 7:30 - 11:00

PERMITTEE <u>The General Crushed Stone</u>	TOWNSHIP <u>E. ROCKHILL</u>	COUNTY <u>BERKS</u>	PERMIT NO. <u>79745M</u>
ADDRESS <u>P.O. BOX 231</u> <u>ERSTOWN, PA 18042</u>	VIOLETION HISTORY ____NOV'S ____CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal _____ Complete <input checked="" type="checkbox"/> Partial or Followup _____		LICENSE NO. & EXP. DATE <u>73-12-81-95</u>	
		OPERATIONAL STATUS <u>ACTIVE</u>	

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500 X 900 X 250 - 5 LIFTS
OPEN PIT QUARRY

b. Acreage (total): Bonded 104.2 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAUR

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Handing					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					763 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Farming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED - EQUIPMENT PACKED AND SITE
NO ONE ON SITE

Person Contacted <u>Copy Mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>[Signature]</u>	Investigator Signature & I.D. No. <u>[Signature]</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name ROCK HILL
Weather Sunny

INSPECTION REPORT
NONCOAL

Date 5-28-95

On Site Times AM

PERMITTEE <u>The GENERAL Crushed Stone Company</u>	TOWNSHIP <u>E Rockhill</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>7974 Sm1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED PREVIOUS VIOLATIONS: CORRECTED UNCORRECTED	FOLLOW-UP INSP. REQUIRED COMPLIANCE ORDER FTC ORDER CEASE ORDER OUTSTANDING ENFORCEMENT
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>238-12-31-95</u>	
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>1500X900X250-561FTS OPEN PIT & HARRY</u>		OPERATIONAL STATUS <u>ACTIVE</u>	

b. Acreage (total): Bonded 1.04 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) None

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hndng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
<input checked="" type="checkbox"/>	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement				<input checked="" type="checkbox"/>	761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes					762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: NO PROB. ON SITE
WATER IN PIT RISING
NO PROBLEM OBSERVED

Person Contacted	Title	Discharge/Sleeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
Signature <u>Copy Office</u>	Investigator Signature & I.D. No. <u>James Carpenter</u>	<input type="checkbox"/> 4 <input type="checkbox"/> 8 <input type="checkbox"/> 0 <input type="checkbox"/> 6

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Date 8-12-95

Mine Name ROCK HILL
Weather SUNNY

INSPECTION REPORT
NONCOAL

Or Site Times AM

PERMITTEE <u>The General Crushed Stone Company</u>	TOWNSHIP <u>EAST ROCKHILL</u>	COUNTY <u>BUCKS</u>	PERMIT NO. <u>79745m1</u>
ADDRESS <u>P.O. Box 231 EASTON, PA 18042</u>	VIOLETION HISTORY <u>NOV'S</u> <u>CO'S</u>	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: <u>CORRECTED</u> <input type="checkbox"/> <u>UNCORRECTED</u> <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
LICENSE NO. & EXP. DATE <u>200733-12-31-95</u>			OPERATIONAL STATUS <u>ACTIVE</u>

GENERAL MINING INFORMATION: Large Noncoal Small Noncoal Complete Partial or Followup

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1566 x 900 x 250-5 LIFTS
OPEN PIT QUARRY

b. Acreage (total): Bonded 104 Affected ALL Regraded 0 Reclaimed 0

c. Equipment-Use & Conditions: SAME

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Store/Handling					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
<input checked="" type="checkbox"/>	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures				<input checked="" type="checkbox"/>	745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
<input checked="" type="checkbox"/>	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
<input checked="" type="checkbox"/>	723 Blasting Requirement					761 Postmining Land Use			
<input checked="" type="checkbox"/>	727 Disposal of Solid Wastes				<input checked="" type="checkbox"/>	762 Cleanup			
<input checked="" type="checkbox"/>	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE LOCKED AT RR.

NO ONE ON SITE

NO PROBLEM OBSERVED

Person Contacted <u>Copy Mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
Signature <u>[Signature]</u>	Investigator Signature & I.D. No. <u>Thomas Carpenter</u>	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no
		Range of Samples Collected _____ to _____
		<u>4 5 0 6</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill Quarry
Weather raining - cold
(610) 253-4271

INSPECTION REPORT
NONCOAL

Date 12/11/96

On Site Times 1:00 PM - 4:00 PM

PERMITTEE <u>Milestone Materials, Inc.</u>	TOWNSHIP <u>East Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>79745M1</u>
ADDRESS <u>P.O. Box 231</u> <u>1900 Sullivan Trail</u> <u>Easton, PA. 18044</u>	VIOLATION HISTORY <input type="checkbox"/> NOV'S <input type="checkbox"/> CO'S	VIOLATIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>			LICENSE NO. & EXP. DATE <u>3-00679 9/30/97</u>
a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: <u>Diorase - open pit quarry</u> <u>~1500ft x 900ft x ~250ft - 5 lifts</u>			OPERATIONAL STATUS <u>Active??</u>

b. Acreage (total): Bonded (103.2) 103.2 Affected ~103.2 Regraded --- Reclaimed ---

c. Equipment-Use & Conditions: To be determined

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) (To be determined)

PERFORMANCE STANDARDS NONCOAL									
Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
<input checked="" type="checkbox"/>	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Store/Handling					735 Revegetation			
<input checked="" type="checkbox"/>	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities				<input checked="" type="checkbox"/>	749 General Safety			
	709 Sedimentation Ponds				<input checked="" type="checkbox"/>	753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
<input checked="" type="checkbox"/>	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: I.D. sign is posted. Site entrance has gate locked. No one is on site. Garage, scalehouse, and other buildings are boarded closed. This site has not been worked since 1991-2 as determined from past inspection reports. Inspector will contact the Operator to verify that a minimum of 500 tons of material has been removed from site in order to retain an active status. Water monitoring reports are up-to-date. There is no violation history for the past 2 years.

Person Contacted <u>Copy to be mailed</u>	Title	Discharge/Seeps <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
Signature	Investigator Signature & I.D. No.	Samples Collected <input type="checkbox"/> yes <input checked="" type="checkbox"/> no ?
	<u>John Embert</u>	Range of Samples Collected _____ to _____
		<u>4 5 0 5</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.

MINING

DISTRICT FILE

COMMONWEALTH OF PENNSYLVANIA
DEPARTMENT OF ENVIRONMENTAL RESOURCES
BUREAU OF MINING AND RECLAMATION

Mine Name Rock Hill
Weather RAIN

INSPECTION REPORT
NONCOAL

Date 10-31-97

On Site Times AM

PERMITTEE <u>The General Crushed Stone Co</u>	TOWNSHIP <u>E. Rockhill</u>	COUNTY <u>Bucks</u>	PERMIT NO. <u>7974SM1</u>
ADDRESS <u>P.O. Box 231</u> <u>Easton, PA 18042</u>	VIOLETION HISTORY NOV'S CO'S	VIOLETIONS NOTED <input type="checkbox"/> PREVIOUS VIOLATIONS: CORRECTED <input type="checkbox"/> UNCORRECTED <input type="checkbox"/>	FOLLOW-UP INSP. REQUIRED <input type="checkbox"/> COMPLIANCE ORDER <input type="checkbox"/> FTC ORDER <input type="checkbox"/> CEASE ORDER <input type="checkbox"/> OUTSTANDING ENFORCEMENT <input type="checkbox"/>
GENERAL MINING INFORMATION: Large Noncoal <input checked="" type="checkbox"/> Small Noncoal <input type="checkbox"/> Complete <input checked="" type="checkbox"/> Partial or Followup <input type="checkbox"/>		LICENSE NO. & EXP. DATE <u>300733-12-31-95</u>	
OPERATIONAL STATUS <u>ACTIVE</u>			

a. Areas-Minerals-Pit Dimensions (L/W/H)-Method: 1500 X 900 X 250-5 LIFTS
ORP

b. Acreage (total): Bonded 104 Affected ALL Regraded Reclaimed

c. Equipment-Use & Conditions: STAKE

d. Contract Miner yes no e. Blasting at Site yes no (Explain yes answers) NONE

PERFORMANCE STANDARDS NONCOAL

Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date	Obs.	STANDARD	PC or Reg.	Viol.	Comp. Date
<input checked="" type="checkbox"/>	700 Unauthorized Mining					730 Concurrent Reclamation			
	701 Signs and Markers					731 Backfilling and Grading			
	702 Casing and Sealing Drilled Holes					733 Covering Coal and Acid/Toxic Mat			
	703 Topsoil-Rem/Sto/Hpdng					735 Revegetation			
	704 Effluent Standard					742 Permanent Mining Cessation			
	706 Diversions and Conveyance					743 Haul Roads/Restoration			
	707 Sediment Control Measures					745 Support Facilities			
	708 Treatment Facilities					749 General Safety			
	709 Sedimentation Ponds					753 Permit Conditions			
	710 Discharge Structures					754 Temporary Mining Cessation			
	711 Acid and Toxic Forming Spoil					755 Closing Underground Mine Openings			
	712 Impoundments					756 Distance Limitations-Barriers			
	713 Dams, Ponds-Design/Const/Maint.					757 Bench Development			
	715 Water Monitoring-Ground/Surface					758 Permit Line Setback			
	717 Water Rights and Replacement					759 Stability Analysis			
	718 Water Discharge-Underground Mine					760 Post Mining Renovation			
	723 Blasting Requirement					761 Postmining Land Use			
	727 Disposal of Solid Wastes					762 Cleanup			
	728 Air Resources Protection								

COMMENTS AND RECOMMENDATIONS: GATE AT RR LOCKED

NO ONE ON SITE

Person Contacted	Title	Discharge/Seeps <input type="checkbox"/> yes <input type="checkbox"/> no
		Samples Collected <input type="checkbox"/> yes <input type="checkbox"/> no
Signature <u>Copy to Cam</u>		Range of Samples Collected _____ to _____
		Investigator Signature & I.D. No. <u>Jonas Carpenter</u> <u>4506</u>

The Operator's signature acknowledges that he has read the report, including the reverse side, and that he was given the opportunity to discuss it with the investigator. The signature does not necessarily mean he agrees with the report.