



**NARRATIVE REPORT FORM**

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609 \_\_\_\_\_

Inspection Date: 9-15-25		Inspection Time: 8:55		Lat/Long:	
Program: ECB		<input type="checkbox"/> Storage Tanks		<input type="checkbox"/> HSCA	
				<input checked="" type="checkbox"/> LRP	
Owner Name: Energy Transfer			Inspection ID:		Site ID:
Facility Location (911) Address: Glenwood Drive and Walker Road Washington Crossing, PA 18977				Municipality: Upper Makefield Twp.	
				County: Bucks	
Responsible Official Name: Brad Fish				Responsible Official Address:	
Title: Senior Environmental Specialist Emergency Response & Remediation				100 Green Street Marcus Hook, PA 19061	
Responsible Official Telephone: 610-859-6297					
Email Address: bradford.fish@energytransfer.com					
<b>Entities Present:</b> DEP – Rebecca Flannery GES – Mike Haezebrouck and Ariana Miranda(drilling) – Devin Graham and Andy Walleth (gauging) ET – Chris Embry, Elijia Contreas, Conner Morris (122 Walker); Wassim Saad, Joe Massaro, Nancy Sadlon and Christ Embry (128 Walker) Stantec - Air and Sound Monitoring Summit Drilling – Monitoring well installation Raab Drilling – Potable well installation					
Purpose: Oversight of monitoring well MW-13S installation at [REDACTED]					
Weather: Partly sunny; 80's					
<b>Narrative:</b> <u>Monitoring well MW-13S</u> <ul style="list-style-type: none"> <li>- The drilling began at 10:00am and stopped at 10:33 when the target depth of 40 feet bgs was reached.</li> <li>- Soil samples were collected every 5 feet for logging and screening purposes.</li> <li>- All the drill cuttings and water were placed into 55-gallon drums to be properly disposed of at a later time.</li> <li>- Saprolite was encountered at a depth of approximately 8 feet bgs, competent bedrock was encountered at a depth of 18 feet bgs and groundwater was at 35.5 feet. There was also a slight PID reading of 1.7ppm when the water was encountered.</li> </ul> <u>Potable well installation at [REDACTED]</u> <ul style="list-style-type: none"> <li>- Raab Drilling began the installation of the new potable well at 12:27pm.</li> <li>- A lined containment was placed under the drill rig to collect drill cuttings and water.</li> <li>- The drill cuttings were placed into a skidster then dumped into a roll-off on a truck.</li> <li>- I noticed occasional petroleum odors while the drilling was going on.</li> <li>- There PID readings, with the highest being of 14.0ppm at a depth of 33 feet bgs.</li> <li>- Groundwater was encountered at a depth of 58 feet bgs.</li> <li>- Drilling was paused at 14:17 at 60 feet bgs to request a vacuum truck to the site to be able to collect all the water coming from the well hole.</li> <li>- I noticed a small sheen on the water in the containment area, but I observed drips of fluid dripping from the drill rig.</li> <li>- Drilling restarted at 15:13 and stopped at 16:10 when the target depth of 81 feet was reached.</li> </ul>					

DEP Representative Name Rebecca Flannery		DEP Representative Signature Rebecca Flannery <small>Digitally signed by Rebecca Flannery Date: 2025.09.23 08:56:04 -0407</small>		Title Geoscientist	
				Date: 9-23-25	
				Telephone: 484-250-5779	
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.					
Interviewee Name		Interviewee Signature		Title	
				Date:	
				Telephone:	



### NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609 \_\_\_\_\_

**Narrative (continued):**

Residential Interactions:

- [REDACTED]
- I stopped by at 11:01 to speak to the resident regarding their inquiry of low water pressure in their house.
- They stated that Suburban Water was there on September 10, 2025, and added air to their pressure tank and turned the pressure up a bit.
- The water pressure was improved, but was told by Suburban that it might only work for a little while.
- I asked them to let us know if the pressure decreased again.

- [REDACTED]:
- I was approached by the resident living at [REDACTED]. Chris E of ET and I spoke with [REDACTED].
- They told me that Suburban was out to their house and replaced their pressure tank since it had sediment in it, which they then had usable water pressure.
- They also showed me a sample of their water from before it enters the pressure tank; it was light olive green in color and had an earthy smell.
- I told [REDACTED] in my opinion that it was probably sediment that got stirred up from the recent drilling activities.
- I asked [REDACTED] to send the details and a picture of the water to the Upper Makefield RA account and we would respond to them.

Chris asked me for [REDACTED] email address, I told him that I would get it for him once [REDACTED] email was sent to the RA account.

I departed the site at 16:25



DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery <small>Digitally signed by Rebecca Flannery Date: 2025.09.23 08:57:00 -0400</small>	Title Geoscientist	Date: 9-23-25
			Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date:
			Telephone:

## NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609

### MAPS / PHOTOGRAPHS / ATTACHMENTS



<b>DEP Representative Name</b> Rebecca Flannery	<b>DEP Representative Signature</b> Rebecca Flannery <small>Digitally signed by Rebecca Flannery Date: 2025.09.23 08:57:25 -0400'</small>	<b>Title</b> Geoscientist	<b>Date:</b> 9-23-25 <b>Telephone:</b> 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
<b>Interviewee Name</b>	<b>Interviewee Signature</b>	<b>Title</b>	<b>Date:</b> <b>Telephone:</b>

### NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609



Drill rig set up at [redacted]  
9-15-25 @ 9:37am



Sound barriers set up at [redacted]  
9-15-25 @ 9:39



Coal shale on water from monitoring well MW-13S at [redacted]  
9-15-25 @10:34



5 feet -----> 40 feet  
Soil samples from every 5 feet while installing MW-13S  
9-15-25 @10:35

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery <small>Digitally signed by Rebecca Flannery Date: 2025.09.23 08:57:51 -0400</small>	Title Geoscientist	Date: 9-23-25
			Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date:

**NARRATIVE REPORT FORM**

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609



Drill rig set up at [redacted]  
 9-15-25 @ 12:28



Water from installing potable well at [redacted] before going  
 into the vacuum truck on site  
 9-15-25 @ 15:35



0 feet -----> 55 feet  
 60 feet -----> 80 feet  
 Soil samples every five feet in new potable well at [redacted]  
 from 0-81 feet bgs  
 9-15-25 @ 16:11

Intentionally Left Blank

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery <small>Digitally signed by Rebecca Flannery Date: 2025.09.23 08:58:14 -0400</small>	Title Geoscientist	Date: 9-23-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date: