



NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road:

Primary Facility ID: 881609 _____

Inspection Date: 10-29-25		Inspection Time: 8:48		Lat/Long:	
Program: ECB		☐ Storage Tanks		☐ HSCA	
				☒ LRP	
Owner Name: Energy Transfer			Inspection ID:		Site ID:
Facility Location (911) Address: Glenwood Drive and Walker Road Washington Crossing, PA 18977				Municipality: Upper Makefield Twp.	
				County: Bucks	
Responsible Official Name: Brad Fish				Responsible Official Address:	
Title: Senior Environmental Specialist Emergency Response & Remediation				100 Green Street Marcus Hook, PA 19061	
Responsible Official Telephone: 610-859-6297					
Email Address: bradford.fish@energytransfer.com					
Entities Present:					
DEP – Rebecca Flannery					
ET – Richard Hamm, Shannon Clemens, Jason Beckner, Wassim Saad					
OTIS Minnesota – Excavation Company					
PHSMA – Nita Raju					
Upper Makefield: Judy Caporiccio					
Earth Data: Dave Fennimore					
Purpose: Observe the uncovering of the pipeline along Taylorsville Road					
Weather: Cloudy and mid-50's					
Narrative:					
I arrived at the excavation site at 8:48am to observe the uncovering of the pipeline to determine if there was any evidence of a release. The excavation was part of routine maintenance for the pipeline. (see map below with red mark)					
The excavation of the soil had already begun when I arrived. There was one pile of soil, which was later informed that it was the topsoil that was going to be placed back on top after the replacement was performed.					
I was asked by the foreman for OTIS what to do with the water from the excavation. I informed him that the Department recommends having a vacuum truck to pump it out.					
As the excavation of the soil proceeded, it would stop about every 2-3 feet so that a metal pole could be used to determine how much further was needed to reach the pipe. (see picture below)					
I observed that about the top 6 feet of soil was tan, with rock fragments. It then turned into a tight grey/blue clay also with rock fragments to the bottom of the excavation was approximately 12-13 feet below ground surface (bgs). The soil on each side of the pipeline was carefully excavated to within about 2 feet from the pipe. I did not notice any odors while the soil was being excavated. Some water did infiltrate into the bottom of the excavation, there was no sheen observed on the water.					
At 13:35 as shoring was being unloaded onto the site to stabilize the excavation I departed.					



DEP Representative Name	DEP Representative Signature	Title	Date: 10-28-25
Rebecca Flannery	Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.10.30 15:33:18 -0400	Geoscientist	Telephone: 484-250-5779
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date:
			Telephone:

NARRATIVE REPORT FORM

Facility Name: Glenwood Drive and Walker Road

Primary Facility ID: 881609

MAPS / PHOTOGRAPHS / ATTACHMENTS



DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.10.30 15:33:34 -0400	Title Geoscientist	Date: 10-27-25 Telephone: 484-250-5779
Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.			
Interviewee Name	Interviewee Signature	Title	Date: Telephone:

NARRATIVE REPORT FORM

 Facility Name: Glenwood Drive and Walker Road

 Primary Facility ID: 881609


Looking northeast from excavation to the canal
9-29--25 @ 9:10



Metal probe used to determine pipeline location
9-29-25 @ 10:14



Pipeline
9-29 @ 13:24



Water in excavation; no visual signs of impacts
9-29-25 @ 12:34

DEP Representative Name Rebecca Flannery	DEP Representative Signature Rebecca Flannery Digitally signed by Rebecca Flannery Date: 2025.10.30 15:33:51 -0400	Title Geoscientist	Date: 10-28-25 Telephone: 484-250-5779
<i>Signature by the person interviewed does not necessarily imply concurrence with the findings on this report but does acknowledge that the person was shown the report or that a copy was left with the person.</i>			
Interviewee Name	Interviewee Signature	Title	Date: